(i.e. 5)	3	Plumbing Followup List (Updated April 12, 2016)								
1   8   PII (b) (6)   PII (b	Number	CODE	Name	Address	Phone	Date Sampled	Data Review: estimates/notes	Date of Plumbing Inspection		
3	1		PII (b) (6)	PII (b) (6)	PII (b) (6)	1/28/2016	Copper inside, likely galvanized at meter of fittings	3/21/2016		
4	2	b	PII (b) (6)	PII (b) (6)	PII (b) (6)	1/28/2016	Probable lead public side; possible galvanized inside	3/21/2016		
S   I   P I (b) (6)	3	d	PII (b) (6)	PII (b) (6)	PII (b) (6)	1/28/2016	Possible LSL, low, copper/galvanized inside	4/9/2016		
6 m PII (b) (6) PI	4	g	PII (b) (6)	PII (b) (6)	PII (b) (6)	1/31/2016	Partial LSL, copper inside	3/21/2016		
7	5	ì	PII (b) (6)	PII (b) (6)	PII (b) (6)	2/1/2016	Probable partial LSL, copper SL	3/23/2016		
7	6	m	PII (b) (6)	PII (b) (6)	PII (b) (6)	2/3/2016	Copper inside	3/22/2016		
S		NAME OF				A STATE OF THE STA	COSCOPI SERVICE SAME ASSAULT APPRENSES	Reveals System Control of the Contro		
9		500				10.00				
10										
11						10.00 P. C.	CHANNEL SOLUTION CONTRACTOR OF THE SOLUTION OF	ANY PROPERTY OF THE PROPERTY O		
13	209033	24					Comment of the Commen			
13   W   P I (b) (6)   PII (										
15			PII (b) (6)				Color	The Art of		
15	14	v	PII (b) (6)	PII (b) (6)	PII (b) (6)	2/7/2016	Possible galvanized	scheduled for 4/18 @ 11:30		
16					A SER SER	1 5 8	-			
17	-				1 11 (8) (8)		A STATE OF THE PARTY OF THE PAR	STOR GP9730CCCCTEG		
18 am	100000	10 (00.00)			PII (b) (6)					
19   as   P I (b) (6)   P I		15				0.51 062				
Addresses Below Added on March 23, 2016   PII (b) (6)								The Part of the Control of the Contr		
Addresses Below Added on March 23, 2016  21		NAME OF TAXABLE PARTY.		The state of the s		CONTROL CONTRO	Copper/galvanized inside, possible galvanized portion	HOME CONTROL CONTROL		
21					Addresses Polow	Added on March 22, 20				
time. Unable to leave VM    Copper pipe coming into the house. Galvanized pipe going through house after the meter. Checked galvanized pipe with magnet and and the magnet stuck.    PII (b) (6)		21/	PII (b) (6)	PII (b) (6)				Called (v0) busy signal each		
22	21	av	111(0)(0)	1 II (b) (0)	11 (0) (0)	2/10/2010	rve in parts of basement			
22							Copper pipe coming into the house. Galvanized pipe	3/31/2016		
ax	22						going through house after the meter. Checked galvanized			
Description of the price of t	22			127	20		pipe with magnet and and the magnet stuck.			
bi PII (b) (6) PII (b) (b) PII		ax				2/11/2016				
24	23	bf	PII (b) (6)	PII (b) (6)	PII (b) (6)	2/13/2016	One run of galvanized (less Than 5 ft) then all copper	4/9/2016		
24   bypassed.   bypassed.   was unwelcoming to EPA		bi	PII (b) (6)	PII (b) (6)	PII (b) (6)	2/15/2016	Lead to house. PVC in house. Whole house filter being	scheduled for 3/31. Resident		
26         cc         PII (b) (6)         PII (b) (6)         PII (b) (6)         4/7/2016         4/7/2016           27         cd         PII (b) (6)         PII (b) (6)         2/18/2016         80 feet         3/28/2016           28         ct         PII (b) (6)         PII (b) (6)         PII (b) (6)         Galvanized appears to run throughout the house. Galvanized under the kitchen sink.         scheduled for 4/18 @ 8am           29         cw         PII (b) (6)         PII (b) (6)         2/20/2016         About 40 ft of pipes from the water main to the water meter         4/2/2016	24						bypassed.	was unwelcoming to EPA		
26         cc         PII (b) (6)         PII (b) (6)         2/18/2016         Galvanized.         4/7/2016           27         cd         PII (b) (6)         PII (b) (6)         2/18/2016         80 feet         3/28/2016           28         ct         PII (b) (6)         PII (b) (6)         2/20/2016         Galvanized appears to run throughout the house. Galvanized under the kitchen sink.         scheduled for 4/18 @ 8am           29         cw         PII (b) (6)         PII (b) (6)         2/20/2016         About 40 ft of pipes from the water main to the water meter         4/2/2016	25	bj	PII (b) (6)	PII (b) (6)	PII (b) (6)	2/16/2016	PVC ON MAIN FLOOR	3/25/2016		
27         cd         PII (b) (6)         PII (b) (6)         PII (b) (6)         2/18/2016         80 feet         3/28/2016           28         ct         PII (b) (6)         PII (b) (6)         PII (b) (6)         Galvanized appears to run throughout the house. Galvanized under the kitchen sink.         scheduled for 4/18 @ 8am           29         cw         PII (b) (6)         PII (b) (6)         2/20/2016         About 40 ft of pipes from the water main to the water	26					2/18/2016	Galvanized.	4/7/2016		
28 ct PII (b) (6) PII (b) (b) (6) PII (b) (b) (6) PII (b) (b) (b) PII (b) (b) (b) PII (b) (b) PII (b) (b) PII (b)	27	cd	20 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0			2/18/2016	80 feet	3/28/2016		
29 cw PII (b) (6) PII (b) (6) PII (b) (6) 2/20/2016 About 40 ft of pipes from the water main to the water meter 4/2/2016 meter	28					2/20/2016		scheduled for 4/18 @ 8am		
	29	cw	PII (b) (6)	PII (b) (6)	PII (b) (6)	2/20/2016	About 40 ft of pipes from the water main to the water	4/2/2016		
I TO THE PARTY OF	30	ds	PII (b) (6)	PII (b) (6)	PII (b) (6)	2/26/2016	Copper line with brass fittings then PVC	3/29/2016		

31	aj	PII (b) (6)	PII (b) (6)	PII (b) (6)	2/10/2016	Copper plumbing.	3/25/2016
32	al	PII (b) (6)	PII (b) (6)	PII (b) (6)	2/10/2016	Appears t be copper, not magnetic, greenish sheen	4/6/2016
33	cf	PII (b) (6)	PII (b) (6)	PII (b) (6)	2/18/2016	About 55 ft of pipes	3/30/2016
34	ci	PII (b) (6)	PII (b) (6)	PII (b) (6)	2/18/2016	Copper before and after water meter and visible in basement. Copper under kitchen sink.	3/28/2016
35	CS	PII (b) (6)	PII (b) (6)	PII (b) (6)	2/20/2016	Copper to meter, copper after meter, brass fittings.	4/5/2016
36	cv	PII (b) (6)	PII (b) (6)	PII (b) (6)	2/20/2016	Copper under sink	3/29/2016
37	db	PII (b) (6)	PII (b) (6)	PII (b) (6)	2/22/2016	Copper to meter, brass fittings, copper throughout house.	4/7/2016
38	dd	PII (b) (6)	PII (b) (6)	PII (b) (6)	2/22/2016	Copper from the ground through out the office building. Other PVC pipes used to connect to the warehouse	4/5/2016
39	df	PII (b) (6)	PII (b) (6)	PII (b) (6)	2/23/2016	Copper to meter, brass fittings, copper throughout house	3/31/2016
40	dh	PII (b) (6)	PII (b) (6)	PII (b) (6)	2/23/2016		4/6/2016
41	dk	PII (b) (6)	PII (b) (6)	PII (b) (6)	2/24/2016	Copper pipes.	4/1/2016
42	dt	PII (b) (6)	PII (b) (6)	PII (b) (6)	2/26/2016	Copper into house. Copper after the water meter.	3/30/2016
43	bs	PII (b) (6)	PII (b) (6)	PII (b) (6)	2/16/2016	Galvanized pipe run to the water meter than copper pipe throughout house service.	
44	CZ	PII (b) (6)	PII (b) (6)	PII (b) (6)	2/21/2016	Basement: Galvanized from wall to the meter then copper through upstairs	4/14/2016
45	dc	PII (b) (6)	PII (b) (6)	PII (b) (6)	2/22/2016	Copper throughout the house.	4/1/2016
46	di	PII (b) (6)	PII (b) (6)	PII (b) (6)	2/26/2016	Galvanized service with copper plumbing throughout basement	4/4/2016
47	ah	PII (b) (6)	PII (b) (6)	PII (b) (6)	2/9/2016		Resident not interested.
48	ai	PII (b) (6)	PII (b) (6)	PII (b) (6)	2/9/2016		4/13/2016
49	ax2	PII (b) (6)	PII (b) (6)	PII (b) (6)	2/13/2016		4/4/2016
50	ae	PII (b) (6)	PII (b) (6)	PII (b) (6)	2/9/2016	Copper service line into house was replaced prior to 1993.	4/8/2016
52	ag	PII (b) (6)	PII (b) (6)	PII (b) (6)	2/9/2016	Possible lead line leading to the house	Does not want PI (3/30 JB)
53	az	PII (b) (6)	PII (b) (6)	PII (b) (6)	2/12/2016		Phone is disconnected (3/30)
54	bb	PII (b) (6)	PII (b) (6)	PII (b) (6)	2/12/2016	Inconclusive, not galvanized. Looks like painted copper but can't be sure.	3/25/2016
55	be	PII (b) (6)	PII (b) (6)	PII (b) (6)	2/12/2016		4/5/2016
56	bg	PII (b) (6)	PII (b) (6)	PII (b) (6)	2/12/2016		4/8/2016
57	СХ	PII (b) (6)	PII (b) (6)	PII (b) (6)	2/21/2016	I SI mamayal hama	4/7/2016
58		PII (b) (6)	PII (b) (6)	PII (b) (6)	Pre-removal 3/11/16; post removal 3/21/16	LSL removal home	3/14/2016
59		PII (b) (6)	PII (b) (6)	PII (b) (6)	pre-removal 3/15/16; post removal 3/28/16	LSL removal home (Renter PII (b) (6)	3/15/2016

60	PII (b) (6)	PII (b) (6)	( ) ( )	Pre-removal 3/5/16; post removal 3/13/2016	LSL removal home	4/13/2016
61	PII (b) (6)	PII (b) (6)		Pre-removal 1/29/16; post-removal 3/11/16	LSL removal home	4/11/2016
62	PII (b) (6)	PII (b) (6)	( ) ( )	Pre-removal 3/5/16; post-removal 3/29/16	LSL removal home	4/13/2016
63	PII (b) (6)	PII (b) (6)	( ) ( )		LSL removal home (renter PII (b) (6)	3/17/2016